



We will be meeting **June 1<sup>st</sup>, Saturday**

at Paul Branchfield's (KJ7BFQ) barn at **9AM** to build the 2 meter copper cube antenna. Directions are below. Please bring the following items/tools if you have them:

Tools to work with copper pipe ½ inch in diameter, propane torch, solder, flux, steel wool, emery cloth to clean joints, tubing cutter, vice grip pliers for heat sink, carpenters square, measuring tape, pencil or sharpie. If you have a flat stone or brick about a foot square to solder on.

Bring food and drink for the day please.

To Paul Branchfield's Barn  
From I-5, Either Direction

Take Exit 119, the Winston exit. Turn Right at the first stoplight. Go about 1 mile, and turn Left the next stoplight. This is East Happy Valley Rd. Go about 1 mile, proceed straight through the stop sign. This is now Happy Valley Rd. Cascara Ln. is just short of milepost 4. Turn Right onto Cascara Ln.

From Melrose/Lookinglass

Take Lookinglass Rd. toward Winston. When you come to Happy Valley Rd., turn Left. Go approximately 1 mile, Cascara Ln. leads off to the Left. If you come to Lapp Ln, you've gone too far.

From Winston

Take Lookinglass Rd. toward Lookinglass. When you come to Happy Valley Rd., turn Right. Go approximately 1 mile, Cascara Ln. leads off to the Left. If you come to Lapp Ln, you've gone too far.

On Cascara Lane

About 200 yards up the hill is 331 Cascara. It is a loop driveway. The barn, and parking, is at the top of the loop.

There are limited bathroom facilities, but there are lots of bushes. I will have drinking water available. You are on your own for coffee.

Not a lot of chairs, so if you want to sit down, you may want to bring a chair.